

CONFIRMATORY SAMPLING REPORT ADDENDUM

AOC 726, Zone H



Charleston Naval Complex North Charleston, South Carolina

SUBMITTED TO

U.S. Navy Southern Division Naval Facilities Engineering Command

PREPARED BY CH2M-Jones

January 2008

Revision 0 Contract N62467-99-C-09602

CONFIRMATORY SAMPLING REPORT ADDENDUM

AOC 726, Zone H



Charleston Naval Complex North Charleston, South Carolina

SUBMITTED TO

U.S. Navy Southern Division

Naval Facilities Engineering Command

PREPARED BY CH2M-Jones

January 2008

Revision 0 Contract N62467-99-C-09602 258814.PM.13

Certification Page for Confirmatory Sampling Report Addendum (Revision 0) — AOC 726, Zone H, Charleston Naval Complex

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that the qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

South Carolina Permit No. 21428

Dean Williamson, P.E.

GNV310133631499,DOC/080140001



January 21, 2008

Ms. Stacey French
South Carolina Department of Health and
Environmental Control
Bureau of Land and Waste Management
2600 Bull Street
Columbia, SC 29201

3011 SW Williston Road Gainesville, FL

Gainesville, Fl 32608-3928

CH2M HILL

P.O. Box 147009

Gainesville, FL 32614-7009

TEL 352.335.7991

FAX 352.335.2959

Re: Confirmatory Sampling Report Addendum, AOC 726, Zone H

Dear Ms. French:

Enclosed please find two copies of the Confirmatory Sampling Report Addendum for AOC 726 in Zone H of the Charleston Naval Complex. This report has been prepared pursuant to agreements by the CNC BRAC Cleanup Team for completing the RCRA Corrective Action process.

Please contact me at 352/335-5877, ext. 52280, if you have any questions or comments.

Sincerely,

CH2M HILL

Dean Williamson, P.E.

cc: Sommer Barker/SCDHEC, w/att

Dearl illiam


Dann Spariosu/USEPA, w/att Jeffrey Meyers/Navy, w/att Gary Foster/CH2M HILL, w/att

1 Contents

2	Section	n		Page
3	Acrony	yms a	and Abbreviations	v
4	1.0	oduction	1-1	
5		1.1	Report Background	1-1
6		1.2.	Report Addendum Organization	1-2
7	Figure	1-1	Location of AOC 726, Zone H	1-3
8	Figure	1-2	Aerial Photo of AOC 726, Zone H	1-4
9	Figure	1-3	CSWP Addendum Proposed Sampling Locations	1-5
10	2.0	Field	d Sampling Results	2-1
11		2.1	SVOC Soil Sampling Results	2-1
12		2.2	VOC Soil Sampling Results	2-1
13			2.2.1 Surface Soil VOC Results	2-2
14			2.2.2 Subsurface Soil VOC Results	2-2
15			2.2.3 Conclusions for VOC Sampling	2-2
16	Table 2	-1	SVOC Detections In Surface Soil at AOC 726	2-3
17	Table 2	2-2	SVOC Detections In Subsurface Soil at AOC 726	2-5
18	Table 2	2-3	Benzo(a)pyrene Equivalent Calculations	2-6
19	Table 2	-4	VOC Detections In Surface Soil at AOC 726	2-7
20	Table 2	-5	VOC Detections In Subsurface Soil at AOC 726	2-8
21	Figure	2-1	Soil Sample Locations at AOC 726	2-9
22	3.0	Conc	clusions and Recommendations	3-1

Acronyms and Abbreviations

2	μg/kg	microgram per kilogram
3	μg/L	microgram per liter
4	1,1-DCE	1,1- dichloroethene
5	AOC	Area of Concern
6	BEQ	benzo(a)pyrene equivalent
7	BRAC	Base Realignment and Closure Act
8	CA	Corrective Action
9	CNC	Charleston Naval Complex
10	COC	chemical of concern
11	COPC	chemical of potential concern
12	CS	Confirmatory Sampling
13	CSWP	Confirmatory Sampling Work Plan
14	DAF	dilution attenuation factor
15	DRO	diesel range organics
16	EPA	U.S. Environmental Protection Agency
17	ft bls	feet below land surface
18	HI	hazard index
19	NA	not available
20	NAVBASE	Naval Base
21	NFA	No Further Action
22	RBC	risk-based concentration
23	RCRA	Resource Conservation and Recovery Act
24	SCDHEC	South Carolina Department of Health and Environmental Control
25	SSL	soil screening level
26	SVOC	semivolatile organic compound
27	VOC	volatile organic compound



1.0 Introduction

- 2 In 1993, Naval Base (NAVBASE) Charleston was added to the list of bases scheduled for
- 3 closure as part of the Defense Base Realignment and Closure Act (BRAC), which regulates
- 4 closure and transition of property to the community. The Charleston Naval Complex (CNC)
- 5 was formed as a result of the dis-establishment of the Charleston Naval Shipyard and
- 6 NAVBASE on April 1, 1996.
- 7 Corrective Action (CA) activities are being conducted under the Resource Conservation and
- 8 Recovery Act (RCRA), with the South Carolina Department of Health and Environmental
- 9 Control (SCDHEC) as the lead agency for CA activities at the CNC. RCRA CA activities are
- 10 performed in accordance with the Final Permit (Permit No. SC0 170 022 560). In April 2000,
 - 11 CH2M-Jones was awarded a contract to provide environmental investigation and
- 12 remediation services at the CNC.

13

1.1 Report Background

- 14 On January 9, 2006, SCDHEC issued a letter to the Navy indicating that a new Area of
- 15 Concern (AOC) had been identified at the CNC. The AOC was described as the location at
- 16 which workers from Wyatt and Wyatt Construction Company (Wyatt and Wyatt)
- 17 potentially encountered hazardous constituents while working on a construction project.
- 18 Subsequent to this letter, the new AOC was designated as AOC 726. The location of AOC
- 19 726 at the CNC is shown on Figure 1-1. An aerial photo of the site is shown on Figure 1-2.
- 20 A Confirmatory Sampling Work Plan (CSWP) was prepared to address SCDHEC's request
- 21 for a work plan to assess whether or not a release of hazardous constituents by the Navy
- 22 had occurred at AOC 726. The CSWP, which incorporated SCDHEC comments, was
- 23 approved by the agency on June 8, 2006.
- 24 Subsequent to this approval, the CSWP was implemented. A Confirmatory Sampling (CS)
- 25 Report was prepared and submitted to SCDHEC on September 12, 2006. SCDHEC provided
- 26 comments on this CS Report to the Navy on October 17, 2006. In these comments and
- 27 during the discussions regarding them, SCDHEC indicated that because of the detection of
- 28 diesel range organics (DRO) at several soil sampling locations, the soil should be analyzed
- 29 for semivolatile organic compounds (SVOCs) to allow for an assessment of potential risks.
- 30 In addition, SCDHEC requested that additional soil samples from the AOC 726 area be


GNV310133631496.DOC/080140001 1-1

- 1 collected and analyzed for volatile organic compounds (VOCs) due to concerns about the
- 2 detections of 1,1- dichloroethene (1,1-DCE) in soil at concentrations generally in the range of
- 3 1 to 5 micrograms per kilogram (μ g/kg), which is above the soil screening level (SSL) of 0.95
- 4 μg/kg, at a dilution attenuation factor (DAF) of 1.
- 5 An addendum to the CSWP was subsequently prepared to address these additional
- 6 sampling requests. After review and resolution of SCDHEC comments on the CSWP
- 7 addendum, the proposed sampling activities were implemented in August 2007. The
- 8 proposed sampling locations from the CSWP addendum are shown in Figure 1-3. At the
- 9 three previous soil sample locations, the soil sampling approach was to collect soil samples
- 10 for analysis of SVOCs only. At the new soil sample locations, the soil sampling approach
- 11 was to collect soil samples for analysis of VOCs only. This addendum to the CS Report
- 12 presents the results of those sampling activities and provides recommendations for
- 13 addressing the site.

14 1.2 Report Addendum Organization

- 15 This CS Report Addendum is organized in the following sections:
- 16 Section 1.0, Introduction provides the background to the report addendum as well as
- 17 pertinent information regarding the work performed for the preparation of the addendum.
- 18 Section 2.0, Field Sampling Results provides a summary of the results drawn from the field
- 19 sampling effort performed in preparation of the report addendum.
- 20 Section 3.0, Conclusions and Recommendations provides a summary of the conclusions
- 21 developed according the results of the investigation, as well as recommendations for the
- 22 future.
- 23 All tables and figures are presented at the end of their respective sections.





SECTION 2.0

Field Sampling Results

2.0 Field Sampling Results

2.1 SVOC Soil Sampling Results

- 3 The field and analytical methods used for this CS Report Addendum field effort are the
- 4 same as those previously described in the original CSWP. The soil sample locations for the
- 5 report addendum are shown in Figure 2-1. At each of the three original soil sampling
- 6 locations, DRO was detected during the original sampling. As a result, resampling of these
- 7 locations for analysis of SVOCs was conducted. At each of these locations (726SB004,
- 8 726SB005, and 726SB006) a surface (0 to 1 feet below land surface [ft bls]) and subsurface (3
- 9 to 5 ft bls) soil sample were collected and analyzed for SVOCs using U.S. Environmental
- 10 Protection Agency (EPA) Method SW846 8270. The SVOCs detected in surface and
- 11 subsurface soil samples are summarized in Tables 2-1 and 2-2, respectively, along with the
- 12 appropriate soil chemical of potential concern (COPC) screening criteria used by the CNC
- 13 Partnering Team.

2

23

- 14 It can be seen in Tables 2-1 and 2-2 that no SVOCs in surface or subsurface soil samples
- 15 exceeded both the COPC screening criteria and background (reference) concentrations.
- 16 Therefore, no SVOC COPCs or chemicals of concern (COCs) are identified in these samples.
- 17 The benzo(a)pyrene equivalent (BEQ) value for each soil sample was also determined using
- 18 the standard BEQ equivalent toxicity values. These values are presented in Table 2-3, along
- 19 with a comparison against the CNC sitewide reference concentrations for BEQs. It can be
- 20 seen in Table 2-3 that none of the BEQ results exceeded the BEQ reference concentrations
- 21 (1,340 μg/kg for surface soil and 1,400 μg/kg for subsurface soil). Therefore, BEQs are not
- 22 identified as COCs for this site.

2.2 VOC Soil Sampling Results

- 24 Soil samples for VOC analysis were collected at five locations, 726SB007 through 726SB011,
- 25 as shown in Figure 2-1. At each of these five locations, a surface (0 to 1 ft bls) and subsurface
- 26 (3 to 5 ft bls) soil sample were collected and analyzed for VOCs using EPA Method SW846
- 27 8260B. Detected VOCs for surface and subsurface soil samples are summarized in Tables 2-
- 28 4 and 2-5, respectively, along with the appropriate CNC COPC screening criteria.

2.2.1 Surface Soil VOC Results

- 2 The purpose of the surface soil VOC sampling was to determine whether 1,1-DCE was
- 3 present at the site. 1,1-DCE was not detected in any of the five surface soil samples analyzed
- 4 for VOCs during this investigation. Therefore, 1,1-DCE is not considered a COPC for surface
- 5 soil at the site.

1

- 6 It can be seen in Table 2-4 that several VOCs, primarily methylene chloride, were detected
- 7 in the surface soil samples at concentrations well below the risk-based screening criteria for
- 8 human exposure to soil, but above the SSL screening value (based on a DAF of 1). However,
- 9 none of these VOCs were previously detected in the groundwater samples analyzed at the
- 10 site during the original CSI. Therefore, these chemicals are not considered COPCs for the
- 11 site. Methylene chloride and acetone are recognized by EPA as common laboratory
- 12 contaminants.

13

24

2.2.2 Subsurface Soil VOC Results

- 14 The purpose of the subsurface soil VOC sampling was to determine whether 1,1-DCE was
- 15 present at the site. 1,1-DCE was not detected in any of the five subsurface soil samples
- 16 analyzed for VOCs during this investigation. Therefore, 1,1-DCE is not considered a COPC
- 17 for subsurface soil at the site.
- 18 It can be seen in Table 2-5 that two VOCs, primarily methylene chloride, were detected in
- 19 the surface soil samples at concentrations well below the risk-based screening criteria for
- 20 human exposure to soil but above the SSL screening value (based on a DAF of 1). However,
- 21 neither of these VOCs was previously detected in the groundwater samples analyzed at the
- 22 site during the original CSI. Therefore, these chemicals are not considered COPCs for the
- 23 site. Methylene chloride is recognized by EPA as a common laboratory contaminant.

2.2.3 Conclusions for VOC Sampling

- 25 The resampling of surface and subsurface soil for VOCs confirmed that 1,1-DCE is not
- 26 present in site soils. Several VOCs, primarily common laboratory contaminants, were
- 27 detected in the soil samples. All VOC detections were well below their respective risk-based
- 28 screening criteria for human exposure to soil. Several VOCs were reported to be present at
- 29 concentrations above their respective SSLs (based on a DAF of 1). However, because these
- 30 VOCs have been previously found to be absent from site groundwater, their detection in
- 31 these soil samples at low levels does not present a risk to the groundwater.

GNV310133631498.DOC/080140001 2-2

TABLE 2-1 SVOC Detections In Surface Soil at AOC 726 CS Report Addendum, AOC 726, Zone H, Charleston Naval Complex

	Sampling		Result (µg/kg)	Qualifier	EPA Regio	661	Background	
Chemical	Location	Station ID			Residential (HI=0.1)	Industrial (HI=0.1)	SSL (DAF=10)	(Reference Value)
Di-n-butyl Phthalate	H726SB004	726SB00401	61.9	J	7,800,000	20,000,000	2,500	NA
Di-n-butyl Phthalate	H726SB005	726SB00501	65.9	J	7,800,000	20,000,000	2,500	NA
Acenaphthene	H726SB006	726SB00601	27.8	J	470,000	1,200,000	52,000	NA
Anthracene	H726SB006	726SB00601	52.6	=	2,300,000	61,000,000	230,000	NA
Benzo(a)Anthracene	H726SB006	726SB00601	330	*	87	780	730	838
Benzo(a)Pyrene	H726SB006	726SB00601	316	=	8.7	78	190	874
Benzo(b)Fluoranthene	H726SB006	726SB00601	454	9	8.7	78	190	874
Benzo(g,h,i)Perylene	H726SB006	726SB00601	149	=	NA	NA	NA	NA
Carbazole	H726SB006	726SB00601	23.7	J	3,200	29,000	230	NA
Chrysene	H726SB006	726SB00601	327	=	8,700	78,000	73,000	844
Di-n-butyl Phthalate	H726SB006	726SB00601	47.5	J	7,800,000	20,000,000	2,500	NA
Fluorene	H726SB006	726SB00601	11.5	J	310,000	8,200,000	68,000	NA
Fluoranthene	H726SB006	726SB00601	559		310,000	8,200,000	3,100	NA
Indeno(1,2,3-c,d)pyrene	H726SB006	726SB00601	150	±	87	780	6,400	874
2-Methylnaphthalene	H726SB006	726SB00601	11.1	1	160,000	4,100,000	11,000	NA
Phenanthrene	H726SB006	726SB00601	250	=	NA	NA	NA	NA
Pyrene	H726SB006	726SB00601	607	=	210,000	6,100,000	340,000	NA

TABLE 2-1 SVOC Detections In Surface Soil at AOC 726 CS Report Addendum, AOC 726, Zone H, Charleston Naval Complex

	Complian		Populi	Qualifier	EPA Regio	SSL	Background
Chemical	Sampling Location	Station ID	Result (µg/kg)		Residential (HI=0.1)	Industrial (HI=0.1)	the same of the sa

Notes:

All values are presented in units of micrograms per kilogram (µg/kg)

DAF = dilution attenuation factor

EPA = U.S. Environmental Protection Agency

HI = hazard index

NA = No value is available.

RBC = risk-based concentration

SSL = soil screening level

Data qualifiers:

[=] Detected. The analyte was analyzed for and detected at the concentration shown.[J] Estimated. The analyte was present but the reported value may not be accurate or precise.

TABLE 2-2 SVOC Detections In Subsurface Soil at AOC 726 CS Report Addendum, AOC 726, Zone H, Charleston Naval Complex

Chemical	Sampling Location	Station ID	Result	Qualifier	SSL (DAF=10)	Background (Reference Value)
Di-n-butyl Phthalate	H726SB004	726SB00402	72.7	J	2,500	NA
Benzo(a)Pyrene	H726SB005	726SB00502	99.7	+	190	496
Di-n-butyl Phthalate	H726SB005	726SB00502	62.8	J	2,500	NA
Fluoranthene	H726SB005	726SB00502	15.9	J	3,100	NA
Benzo(a)Pyrene	H726SB006	726SB00602	94.2	J	190	496
Benzo(b)Fluoranthene	H726SB006	726SB00602	18.7	J	190	498
Di-n-butyl Phthalate	H726SB006	726SB00602	42.6	J	2,500	NA
Fluoranthene	H726SB006	726SB00602	11.9	J	3,100	NA

Notes:

All values are presented in units of micrograms per kilogram (µg/kg).

DAF = dilution attenuation factor

NA = No value is available.

SSL = soil screening level

Data qualifiers:

[=] Detected. The analyte was analyzed for and detected at the concentration shown.

[J] Estimated. The analyte was present but the reported value may not be accurate or precise.

GNV310133631498.DOC/080140001 2-5

TABLE 2-3 Calculation of BEQs for Soil Samples at AOC 726

			100	1	H72	6SB004				H7265	\$8005				H7:	26SB006	
	Units	TEF	Surface	726SB00401	Subsurface	726SB00402	Surface	- 7	726SB00501	Subsurface	7	26SB00502	Surface	726SB00601	Subsurface	726SB00602	
PAHs																	
Benzo(a)anthracene	mg/Kg	0.1	38.1 U	1.9050000	41.5 U	2.0750000	38,80000	U	1.9400000	41.7	U	2,0850000	330 =	33.0000000	38 1	3.800000	
Benzo(b)fluoranthene	mg/Kg	0.1	38.1 U	1.9050000	41.5 U	2.0750000	38.80000	U	1.9400000	41.7	U	2.0850000	454 =	45.4000000	18.7 J	1.870000	
Benzo(k)fluoranthene	rng/Kg	0.01	38.1 U	0.1905000	41.5 U	0.2075000	38.80000	U	0.1940000	41.7	U	0.2085000	34.8 U	0.1740000	38 U	0.190000	
Benzo(a)pyrene	mg/Kg	1	38.1 U	19.0500000	41.5 U	20.7500000	38,80000	U	19,4000000	99,7	=	99,7000000	316 =	316,0000000	94.2 J	94.200000	
Chrysene	mg/Kg	0.001	38.1 U	0.0190500	41.5 U	0.0207500	38.80000	u	0.0194000	41.7	U	0.0208500	327 =	0.3270000	38 U	0.019000	
Dibenz(a,h)anthracene	mg/Kg	1	38.1 U	19.0500000	41.5 U	20.7500000	38.80000	U	19.4000000	41.7	U	20.8500000	34.8 U	17.4000000	38 U	19,000000	
Ideno(1,2,3-c,d)pyrene	mg/Kg	0.1	38.1 U	1.9050000	41.5 U	2.0750000	38.80000	U	1.9400000	41.7	U	2.0850000	150 =	15,0000000	38 U	1,900000	
Benzo(a)pyrene Equivalent	(BEQ) concentr	ation (ug/Kg) =	44.0		48.0		44.8			127.0	0		427.3		121.0		

Fraction of "U" data = 0.5 (used in calculation)

TABLE 2-4
VOC Detections In Surface Soil at AOC 726
CS Report Addendum, AOC 726, Zone H, Charleston Naval Complex

				EPA Region III RBC								
Chemical	Sampling Location	Station ID	Result	Qualifier	Residential (HI = 0.1)	Industrial (HI = 0.1)	SSL (DAF=1)					
1,4-Dichlorobenzene	H726SB007	726SB00701	0.469	J	2,700	24,000	0.36					
Methylene Chloride	H726SB007	726SB00701	5.31	=	8,500	76,000	1					
Methylene Chloride	H726SB008	726SB00801	7.8		8,500	76,000	1					
Methylene Chloride	H726SB009	726SB00901	5.88		8,500	76,000	1					
Methylene Chloride	H726SB010	726SB01001	2.99	j	8,500	76,000	1					
Acetone	H726SB011	726SB01101	10.6	=	780,000	20,000,000	800					
Methylene Chloride	H726SB011	726SB01101	7.53	4	8,500	76,000	1					

Notes:

All values are presented in units of micrograms per liter (µg/L). Exceedances of screening criteria are shown in bold text.

DAF = dilution attenuation factor

SSL = soil screening level

Data qualifiers:

[=] Detected. The analyte was analyzed for and detected at the concentration shown.

[J] Estimated. The analyte was present but the reported value may not be accurate or precise.

TABLE 2-5 VOC Detections In Subsurface Soil at AOC 726 CS Report Addendum, AOC 726, Zone H, Charleston Naval Complex

Chemical	Sampling Location	Sample ID	Result	Qualifier	SSL (DAF=1)	
1,4-Dichlorobenzene	H726SB007	726SB00702	0.742	J	0.36	
Methylene Chloride	H726SB007	726SB00702	10.4	11=	1	
Xylenes, Total	H726SB007	726SB00702	0.334	J	10,000	
m+p Xylene	H726SB007	726SB00702	0.334	J	10,000	
Acetone	H726SB008	726SB00802	4.25	J	800	
Methylene Chloride	H726SB008	726SB00802	9.5	=	1	
Acetone	H726SB009	726SB00902	36.2	i di	800	
1,4-Dichlorobenzene	H726SB009	726SB00902	0.344	J	0.36	
Methyl ethyl ketone (2-Butanone)	H726SB009	726SB00902	4.66	- J	400	
Methylene Chloride	H726SB009	726SB00902	6.29	÷	1	
Methylene Chloride	H726SB010	726SB01002	6.06	(=)	1	
Acetone	H726SB011	726SB01102	38.3	=	800	
Methyl ethyl ketone (2-Butanone)	H726SB011	726SB01102	6.62	J	400	
Methylene Chloride	H726SB011	726SB01102	8.02	- 1/2	1	

Notes:

All values are presented in units of micrograms per liter (µg/L). Exceedances of screening criteria are shown in bold text.


DAF = dilution attenuation factor

SSL = soil screening level

Data qualifiers:

[=] Detected. The analyte was analyzed for and detected at the concentration shown.[J] Estimated. The analyte was present but the reported value may not be accurate or precise.

GNV310133631498,DOC/080140001 2-8



SECTION 3.0

Conclusions and Recommendations

3.0 Conclusions and Recommendations

- 2 The additional sampling and analysis at AOC 726 confirmed that the SVOCs do not pose an
- 3 unacceptable risk to human health and the environment, and that 1,1-DCE is not present
- 4 across the site. No SVOC or VOC COCs are identified for AOC 726. Overall, the data
- 5 indicate that additional sampling and analysis is not required. The site is recommended for
- 6 No Further Action (NFA).